



esp

**Environmental &
Safety Professionals**

A division of Enviro-Net Australia Pty. Ltd.
ABN 39 067 499 389 ACN 067 499 389 NATA Reg. 3110
2/2B Parker Street, Footscray, Victoria 3011
Ph: (03) 9688 8000 Fax: (03) 9689 6470
Email: esp@esplabs.com.au

ESP Job No: U1374

Sunday, 14th October, 2012

Property & Campus Services
The University of Melbourne
625-631 Swanston Street
Carlton VIC 3053

Ph: (03) 9035 7564

ATT: Anne Thompson – Project Manager

RE: VISUAL CLEARANCE CERTIFICATE
ARCHITECTURE (BN 133)
GROUND FLOOR CEILING INVESTIGATION

Mr Darren Clerehan of ESP – Environmental & Safety Professionals undertook visual inspections following the ceiling investigations at Architecture Building BN133, Ground floor foyer between 11.30 and 13.30 on the 14th October 2012.

The ceiling investigation works were performed by Chapman Gardner Pty Ltd.

The visual inspection has found that there is no visible asbestos residue present, however scrapings of the ceiling have been collected and returned to ESPs NATA accredited laboratory for analysis.

As part of the ceiling investigation, paraoccupational air monitoring was conducted during and following the investigation works with all tests having results of less than 0.01f/mL (see attached NATA results).

Based on both the visual inspection and air monitoring results, this area is deemed safe to be occupied by unprotected personnel.

Yours sincerely

ESP – ENVIRONMENTAL & SAFETY PROFESSIONALS

Senior Asbestos/Hazardous Materials Consultant